	DPW	Poor	Yes	17"	Blue Spruce	8 Anna St
		Poor	Yes	20"	Red Oak	113 Greenwich Rd
		Poor	Yes	26"	Red Oak	113 Greenwich Rd
	Division III/O Delication	Poor	Yes	12"	S Hickory	113 Greenwich Rd
	THE PERSON NAMED IN COLUMN NAM	Poor	Yes	24"	Oak	113 Greenwich Rd
		Poor	Yes	26"	White Oak	Across 110 Greenwich Rd
		Poor	No	30"	Red Oak	106 Greenwich Rd
		Poor	No	သွ	Red Oak	106 Greenwich Rd
		Poor	No	40"	Red Oak	104 Greenwich Rd
	90% canopy loss	Poor	Yes	28"	Red Oak	100 Greenwich Rd
	Bad crown less than 50%	Fair	No	46"	Sugar Maple	9 Cottage St
	Root Zone is Damaged	Fair/Poor	No	36"	Sugar Maple	16 Elm St
		Poor	Yes	22"	Red Oak	U.P. 12 Millers Rd
		Poor	Yes	20"	Red Oak	U.P. 11-12 Millers Rd
		Poor	Yes	18"	Red Oak	U.P. 11-12 Millers Rd
	The strategic state of the year	Dangerous/Poor	Yes	18"	Red Oak	U.P. 10-11 Millers Rd
		Poor	Yes	30"	Red Oak	U.P. 10 Millers Rd
	THE RESERVE OF THE PARTY OF THE	Poor	Yes	24"	Red Oak	16 Millers Rd
	leave wood	Poor	Yes	18"	White Oak	12 Millers Rd
		Poor	No	12"	Ash	U.P. 6 Stagecoach Rd
		Poor	Yes	42"	Oak	U.P. 4 Stagecoach Rd
		Poor	Yes	40"	Oak	U.P. 3 Stagecoach Rd
		Poor	Yes	40"	Oak	U.P. 3 Stagecoach Rd
		Poor	No	40"	Oak	U.P. 3 Stagecoach Rd
		Poor	No	44"	Oak	131 Church St
		Poor	No	40"	Maple	77 Church St
					180	M. N. LEIL BOTTOM
Action	Notes	Condition	Wires Yes/No	Height (DBH)	Species	Location
				Diameter Breast		

		Poor	No	24"	White Oak	76 River Rd
		Fair/Poor Structure	Yes	34"	White Pine	68 River Rd
		Poor	No	10"	Maple	Bumpy Hill Rd
2 1001 2		Fair	No	18"	Red Oak	66 Fisherdick Rd
		Poor	No	36"	Ash	95 Fisherdick Rd U.P. 22
	leave logs on back side of stone wall	Poor	No	33"	Maple	100 Fisherdick Rd
		Poor	No	20"	Oak	120 Fisherdick Rd
		Poor	No	26"	White Oak	8 Hutchinson Rd
		Poor	Yes	26"	Ash	Corner Lot Greenwich/Fisherdick
		Poor	Yes	28"	Double leader Green Ash	214 Greenwich Plains Rd
	car park under tree to access Quabbin gate	Poor	No	26"/24"	Double leader White Oak	215 Greenwich Plains Rd
	car park under tree to access Quabbin gate	Poor/Failing	No	32"	Red Oak	215 Greenwich Plains Rd
		Poor	No	34"	White Oak	175 Greenwich Plains Rd
		Poor	No	28"	Ash	U.P. 68 Greenwich Plains Rd
		Poor/Fair	No	26"	Sugar Maple	23 Old Poor Farm Rd
		Fair	No	18"	Ash	110 Old Poor Farm Rd
	District in the 18	Poor	No	36"	Ash	254 Osborne Rd building lot
		Poor	Yes	14"	Ash	9 Campbell Rd
		Poor	Yes	22"	Ash	10 Campbell Rd
100		Poor	Yes	28"	Ash	6 Campbell Rd
		Poor	No	34"	White Oak	1 Campbell Rd
	Damaged Root Zone 90% canopy loss	Poor	No	25"	Red Maple	54 Hardwick Pond Rd
Action	Notes	Condition	Wires Yes/No	Diameter Breast Height (DBH)	Species	Location

		D	Vec	40°	White Oak	10 Bandeville Dd
		Poor	Š	24"	Red Oak	Bondsville Rd U.P. 58-50
	4' Stump must remain	Fair	No	30,	White Pine	19 Bondsville Rd
		Poor	Yes	14"	Oak	from each other
	\$112 mile 121 m 1 1	Poor	No	16"	White Oak	from each other
						River Rd across
		Poor	No	30"/24"	Red Oak	175 River Rd opposite side
		Poor	No	24"	White Oak	opposite side
				8	5 7	175 River Rd
		Poor	No	20"	Green Ash	opposite side
						175 River Rd
		Poor	N _o	52"	Red Oak	175 River Rd opposite side
	90% crown loss	Poor	Yes	28"	White Oak	U.P. 40-175 River Rd
	Lamber the planty are stated	Poor	No	20"	Red Oak	173 River Rd
800	many amendment of the sound of	Poor	No	26"	White Oak	173 River Rd
	The second of th	Poor	No	18,	Red Oak	173 River Rd
	State of the late	Poor	No	24"/24"	Multi Leader White Oak	River Rd
		Poor	No	48"	White Oak	River Rd
ıy	Structure issues, internal decay	Critical	No	20"	White Pine	115 River Rd
	Tree has structure issues	Poor	Yes	40"	White Pine	across from 113
						112 River Rd
		Poor	No	22"	White Oak	109 River Rd
Action	Notes	Condition	Yes/No	(DBH)	Species	Location
	The state of the s		Wires	Height	A STATE	
	DETAIL MITHERITY		245	Diameter Breast		

	DOMESTIC DESCRIPTION OF THE PROPERTY OF THE PR	Fair/Poor	No	24"	White Oak	26 Dugan Rd
	unstable stand	Critical	Yes	10" - 24"	Maple (5)	Across from 30 Dugan Rd
	Hollow core unstable	Critical	Yes	42"	Ash	32 Dugan Rd
BOICHA	rotten base	Poor	Yes	42"	Oak	33 Dugan Rd
		Poor	No	01	1 Blue Spruce	74 Anderson Rd
		Poor	No	00 =	2 Blue Spruce	74 Anderson Rd
		Poor	No -	48"	Silver Maple	Across 84 Dugan Rd
	Section 1 and 1 an	Poor	No	39"	Red Maple	89 Dugan Rd
		Poor	No	38"	White Oak	89 Dugan Rd
6.7		Poor	No	18"	Black Cherry	U.P. 2 Sherman Hill Rd
	guy wire attached, leave stem	Critical	No	24"	Poplar	35 Sherman Hill Rd
	Homeowner has structure behind trees	Poor/breaking	Yes	24"	Maple	18 Sygiel Rd
	Homeowner has structure behind trees	Poor/breaking	Yes	20"	Cherry	18 Sygiel Rd
	Homeowner has structure behind trees	Poor/breaking	Yes	22"	Cherry	18 Sygiel Rd
	Trim Red Oak next to, remove all dead wood	Poor	N _o	24"	Red Oak	17 Sygiel Rd
		Poor	No	26"	Red Maple	19 Sygiel Rd
		Poor	No	ည့	Red Oak	21 Sygiel Rd
		Poor	Yes	25"	Poplar	39 Moriarty Rd
	Structure compromised	Failing	Yes	18"	Poplar	47 Moriarty Rd
		Poor	No	26"	Red Oak	Old Belchertown Rd
		Poor	Yes	25"	Green Ash	190 Old Belchertown Rd
	Red reflector	Poor	N _o	16"	Grey Birch	Old Belchertown Rd - in the narrow
	guy wire/ from pole cut to guy wire, leave stem	Poor	No	40"	White Oak	133 Bondsville Rd
		Poor	Yes	22"	White Oak	Bondsville Rd near Murphy
Action	Notes	Condition	Wires Yes/No	Diameter Breast Height (DBH)	Species	Location

adha.			No. in case of	The shall	ı	12 Walker Rd in front
	The second secon	Poor	Yes	12"	Red Maple	12 Walker Rd in front of 7 Howard Rd
	Safety issue/traffic	Fair/Good	Yes	28"	Red oak double	12 Walker Rd/Howard Rd
		Poor	Yes	28"	Red Oak	48/51 Cummings Rd
		Poor	Yes	28"	Red Maple	48/51 Cummings Rd
	Mail region	Poor	Yes	36"	Red Oak	48/51 Cummings Rd
	Blown off bark, structure may be bad	Poor/critical	Yes	24"	Red Oak	107 Walker Rd
	Blown off bark, structure may be bad	Poor/critical	Yes	24"	Red Oak	107 Walker Rd
	resident at 109 wants wood/logs	Poor	N _o	22"	Red Oak	Across from 109 Walker Rd
	resident at 109 wants wood/logs	Fair/Poor	Yes	42"	Red Oak	109 Walker Rd
		Poor	Yes	22"	Red Maple	Gilbertville Rd
			100	100	Mary My Confe	U.P. 50 Old
	The state of the s	Poor	No	24"	Ash	Gilbertville Rd
	The state of the s	THE REAL PROPERTY.		THE STREET	ALL DESKY	Across from 276 Old
	guy wire red oak	Poor	Yes	36"	Red Oak	Old Gilbertville Rd
			A W		W. W	Across from 150
		Poor	Yes	22"	White Oak	Old Gilbertville Rd
		THE STREET	1	**	A Contractor	Across from 150
		Poor	Yes	36"	Red Oak	Across from 150 Old Gilbertville Rd
		Fair/Poor	No	38"	Sugar Maple	Benham Ave/94 South St
3	resident is worried structure has issues	Poor	No	33"	Norway Maple	15 Gould Rd
		Poor	No	40"	Sugar Maple	Across from 8 Dunham Ave
	Overhanging houses	Poor	Yes	36"	Elm	17 Third Ave
		Fair	No	10"-14"	7 Pitch Pines	25 Mountain View Drive
Action	Notes	Condition	Yes/No	(DBH)	Species	Location
			Wires	Diameter Breast Height		

				(0 18%)		
				COMMISSION OF STREET		
				I I		
	No.	STATE STATE	70			TWILLY
		Poor	No	30"	Red Oak	102 Coffey Hill Rd
		Poor	Yes	24"	Red Oak	opposite
		THEST				294 Malboeuf Rd
	大 のました ひとなる かち 十十十	Poor	No	28"	Red Oak	opposite
		TOUT DAME.			THE WAY	294 Malbouef Rd
	large cavity 12 ft	Poor	Yes	32"	Red Oak	284 Malbouef Rd
		Poor	No	10"	Paper Birch	30 Shoreline Dr
		Poor	No	30"	White Oak	23 Beach Rd
		Fair/Poor	Yes	27"	White Oak	183 Monson Turnpike Rd
		Poor	Yes	44"	White Oak	91 Monson Turnpike Rd
	THE TANK OF THE	Poor	No	30"	Red Oak	Town Property James Rd
	leave wood	Poor	No	48"	White Oak	James Rd
	leave wood	Fair/Poor	No	52"	White Oak	James Rd
		Fair	No	26"	Red Maple	7/9 Kelly Rd
		Fair	No	22"	Red Maple	7/9 Kelly Rd
	SOUTH STREET OF THE WORLD THE PROPERTY.	Fair/Poor	No	20"	Black Cherry	5 Kelly Rd
	The state of the s	Poor	Yes	36"	Ash	129 Babcock Tavern Rd
	The state of the s	Fair/Poor	No	26"	Ash	71 Babcock Tavern Rd
	That select multiple multiple receiff	Poor	No	44"	Ash	60 Babcock Tavern Rd
	large rotted cavity in backside of tree in flare	Fair/Poor	No	44.	White Pine	18 Howard Rd
		Poor	Yes	12"	Red Maple	Front of 9 Howard Rd
	Mindran C Ix	Poor	Yes	14"	Red Maple	of 7 Howard Rd
Action	Notes	Condition	Wires Yes/No	Height (DBH)	Species	Location

			Location	
		•	Species	
			Diameter Breast Height (DBH)	List of
			t Wires	Trees for R
		Condition	Condition	List of Trees for Removal Consideration/Action
		Canoni		eration/Action
		Action		